# .30-E (PWM ONLY) 2000-U

**PART NUMBER 54754-02** 

# 1870 TCC slip code, torque converter slip-related problems

The OEM sleeve warps due to large slots, causing the valve to bind up, or leakage occurs due to sleeve wear, resulting in loss of any pressure.


Replace the OEM sleeve with the Sonnax sleeve, which provides added stability and better wear resistance.

## **TCC Regulator** Valve Sleeve

54754-02

1 TCC Regulator Valve Sleeve

• Valve stuck in sleeve • Worn sleeve



## **Sonnax Part Summary**

The OEM TCC regulator valve sleeve is prone to warping because of the large slots on both sides of the sleeve. Once warped, the valve binds and gets stuck in one position or leads to excessive bore wear and circuit leaks. The Sonnax sleeve 54754-02 has reinforcement ribs for added stability and is made from wear-resistant aluminum alloy material. The sleeve is designed for use with the OEM steel valve. This sleeve is a drop-in replacement and does not require machining.

### **Features & Benefits**

- Reinforcement ribs added for sleeve stability.
- Made of wear-resistant aluminum alloy material.
- Drop-in replacement with no machining required.

