096, 097, 098, 01M, 01N, 01P

PART NUMBER 119940-23

COMPLAINT

Loss or bending of operating rod

CAUSE

The manual valve operating rod can become lost or damaged during a rebuild, making it necessary to rob cores for replacement parts.


Correction

Sonnax has developed a direct replacement manual valve operating rod to prevent scrapping of expensive cores.

Manual Valve Operating Rod

119940-23

1 Manual Valve Operating Rod



Sonnax Part Summary

The operating rod (linkage) that connects the selector shaft assembly to the manual valve is often lost or damaged during overhaul. This direct replacement manual valve operating rod is made from hardened steel wire to ensure the proper geometry is retained, and allows units to be salvaged.

Features & Benefits

- Hardened steel wire retains proper geometry.
- Replaces lost or damaged rods.

