

COMPLAINT

Harsh TCC engagement

CAUSE


The OEM TCC accumulator spring can fatigue or break due to stress and material quality.

CORRECTION

The Sonnax spring is manufactured from an upgraded material to increase spring strength and resiliency.

TCC Accumulator Springs

44912-01
5 Springs



Sonnax Part Summary

Harsh TCC engagement complaints can occur due to breakage of the TCC accumulator spring in the pump assembly. The OEM spring material and design is overstressed in this application. The replacement Sonnax spring **44912-01** is manufactured from an upgraded material to increase spring strength and resiliency.

Features & Benefits

- Upgraded material increases spring strength
- Spring rated for “severe duty” allows more life cycle deflections