

COMPLAINT

SECONDARY COMPLAINTS

Poor line rise

- Early soft upshifts • Low line pressure • Premature 3-4 clutch failure

CAUSE

The steel TV plunger wears the TV plunger sleeve, allowing TV feed oil to leak past the plunger and exhaust.

CORRECTION

These valve and sleeve kits restore the hydraulic integrity of the circuit.

Throttle Valve Plunger & Sleeve Kits

77966-93K OEM "#93"

77966-94K OEM "#94"

77966-94MK High Performance


Each kit contains the following

- 1 Plunger
- 1 Sleeve
- 1 Spring

Also Available:

77968-01K

5 TV Plunger Springs



Sonnax Part Summary

Poor line rise or no detent downshifts can be common complaints in vehicles with a THM 700-R4 transmission. The steel throttle valve plunger continuously reciprocates within the aluminum throttle valve plunger sleeve, wearing the sleeve. This wear allows throttle valve feed oil to leak past the plunger and exhaust, resulting in poor line rise and problematic downshifts. In addition, the OEM spring is weak and can result in low line rise, insufficient throttle pressure and, ultimately, 3-4 clutch failure.

Features & Benefits

- Sleeve is made from high-quality aluminum to prevent wear.
- Sleeve and plunger have been tightly toleranced to restore hydraulic integrity.
- Kits include an improved throttle valve spring designed to maintain higher line pressure and improved TV performance.
- High performance kit eliminates the part throttle sleeve orifice, allowing for full throttle upshifts from 3rd gear to overdrive.

