PART NUMBER 84596-01K

COMPLAINT

Worn channel plate sleeve

CAUSE

Drive sprocket, bearing failure cause channel plate (case cover) sleeve wear.

CORRECTION

Replace the worn channel plate sleeve with 4T65-E thru-hardened replacement sleeve.

Channel Plate Sleeve


84596-01K

Channel Plate Sleeve

Also available:

8041

Channel Plate Sleeve for 4T60 & E applications



Sonnax Part Summary

OEM does not service the 4T65-E channel plate sleeve as an individual part. In the past it was necessary to purchase a channel plate (case cover) assembly. Sonnax now offers a replacement thruhardened sleeve, **84596-01K**.

Features & Benefits

- Part is not serviced separately by OEM.
- Sleeve is thru-hardened for greater durability.

