

COMPLAINT

Low line pressure

CAUSE

A broken line pressure regulator valve cushion spring.

CORRECTION

Line Pressure Regulator Valve Cushion Spring

95200-01 Fits Type 1 or Type 2
1 Cushion Spring valve bodies

Also available:

95200-06

1 OEM-sized Pressure Regulator Valve

95200-05K

1 Pressure Regulator Valve Sleeve
1 Clip




95200-TL

1 Reamer
1 Core Drill
1 Reamer Jig
1 Drill Jig

95200-03 Type 2 valve bodies only

1 Boost Valve
1 Boost Sleeve
2 O-Rings



Sonnax Part Summary

The line pressure regulator valve cushion spring commonly breaks, resulting in low line pressure. Replacing the broken spring with Sonnax's spring **95200-01** eliminates the need to replace the upper valve body. While the operating environment is severe for a spring of this size, Sonnax's material minimizes the chance of breakage.

Features & Benefits

- Cushion spring made from rugged chrome-silicon alloy to provide high allowable working stresses.
- Salvages costly valve bodies.