

Features & Benefits:


- Direct OEM replacement
- Hardened and ground for better wear resistance
- Restores pump integrity

Part No.

96200-02

Pump Slide Pin/Bag of 5

Unit Price: \$4.08



PART SUMMARY

Wear of the pump slide pivot pin due to the continuous oscillation of the pump slide allows cross leaks between the pressure and exhaust sides. As the OEM pin wears, it can contribute to erratic pump slide movement, which in turn causes erratic pressures and poor line rise control.

Sonnax replacement pin **96200-02** is a direct replacement for a worn factory part, and restores the integrity of the pump.