


**Features & Benefits:**

- **Through-hardened to prevent excessive wear**
- **Less expensive than OEM**
- **Direct OEM replacement**

**Part No.**

**65797**

5 Pivot pins



**PART SUMMARY**

Vehicles with 4L60 & E and THM 200-4R transmissions can have low or high line pressure due to a worn pump slide pivot pin. Decreased oil pressure meant to maintain proper line pressures can leak past a worn pin. Sonnax now offers a replacement pump slide pivot pin. This direct replacement pin **65797** will help restore the hydraulic integrity of the pump when replacing a worn pin. This pin is made from through-hardened steel to prevent excessive wear.

**INSTALLATION INSTRUCTIONS**

This pin is a direct replacement and will fit 4L60 & E and THM 200-4R pumps. Refer to the photo above for proper position and orientation.